



EST^o 1859

BES Group

REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

Lifting Operations and Lifting
Equipment Regulations 1998
(Regulation 9)

In any correspondence relating to this
report please quote:

District **L654**

Policy **ACT000555118**

Item No. **LA1**

1 Employer (and/or plant owner) **Enterprise House Darlington Limited**

2 Address **S7046218447
Enterprise House
Valley Street North
Darlington
County Durham
DL1 1GY**

For the attention of **Manager**

3 Address at which the examination
was made **As above.**

4 Description of Lifting Equipment **ELECTRIC PASSENGER PLATFORM LIFT**

Distinguishing Number **GAR1702**

Makers Name **ARITCO**

Model **A1**

Year of Manufacture **2006**

Safe Working Load
(As marked, unless otherwise stated) **630 kg / 5 persons**

5 Nature of Examination **Thorough Examination carried out within an interval of 6 months under Regulation 9(3)(a)(i) unless otherwise indicated.**

6 Identification of any part found to
have a defect which is or could
become a danger to persons.
State description of the defect,
and any repair, renewal or
alteration required to remedy the
defect, either immediately or
within a specified time.

7 (i) Other defects and remedies.
(Corrective actions are required
as soon as reasonably
practicable.) **None.**

7 (ii) Details of any tests required to
supplement the examination **None.**

8 Observations **Load nut / screw remain serviceable.**

The Safety Assessment Federation (SAFed) give guidance on supplementary testing of in-service lifts and some of these tests are recommended on a 'periodic' basis and should be considered as part of your routine service regime. We advise the key safety aspects of this lift installation be risk assessed and consideration be given to 'periodic' testing, where applicable, in accordance with the current version of SAFed lift guidelines (LG1).

Where supplementary tests are required to support the thorough examination a request will be made by the competent person.

Note: Design not checked, this report should be read in conjunction with an EC Declaration of Conformity Certificate and/or Initial Thorough Examination Report (inc. load test, where applicable) issued by your manufacturer and/or installer.

9	Date of last thorough examination	29/10/2025
	Date of this examination	17/04/2026
	Latest date by which the next thorough examination must be carried out	17/10/2026

Unless otherwise stated, this inspection has been completed in accordance with Procedure 05-20-P01.

I certify that the above equipment was thoroughly examined (unless otherwise stated) and, subject to any remedial action to defects noted on this report, which are or could become a danger to persons, the equipment is safe to operate.

Date of Examination **17/04/2026**

Report Date **17/04/2026**

Signature: Mr C Jones



Qualification - Engineer Surveyor to
British Engineering Services
Unit 718 Eddington Way, Birchwood Park, Warrington WA3 6BA
Telephone: 0345 712 5842 Web: besgroup.com

L3

vers E.80
ID: 40934631